
DocuSign Envelope ID: 09A74E7D-91FA-4EFC-BFF2-68B612563FD4

NOTES:

1. IRON PINS (1/2") FOUND AT ALL CORNER, UNLESS OTHERWISE NOTED.

2. THIS PROPERTY IS NOT, SITUATED WITHIN A SPECIAL FLOOD HAZARD AREA AS IDENTIFIED BY THE FLOOD INSURANCE RATE MAP (F.I.R.M.) NO. 480290C0297 F, DATED JANUARY 4, 2002.

North
Scale: 1" =20'



SURVEY ACKNOWLEDGED BY:

PROPERTY SURVEY OF:

LOT 16, BLOCK 5, N.C.B. 16616, GARDENHILL SUBDIVISION P.U.D. UNIT 1, AN ADDITION IN THE CITY OF SAN ANTONIO, TEXAS ACCORDING TO THE MAP OR PLAT THEREOF, RECORDED IN VOLUME 9564, PAGE 219, DEED AND PLAT RECORDS OF BEXAR COUNTY, TEXAS.

THIS SURVEY IS ACKNOWLEDGED AND ACCEPTED BY:

Flores & Company Inc.
Consulting Engineers
12915 Jones Maltsberger, Suite 401
San Antonio, Texas 78247
Phone. 210.490.9963 Fax. 210.490.0820

CERTIFICATION

I hereby certify that the above plat is true and correct according to an actual survey made on the ground under my supervision and that there are no visible easements or encroachments of buildings on adjoining property and that all buildings are wholly located on this property except as shown above.

This 17th Day of MAY, 20 06 A.D.

THOMAS FLORES REGISTERED PROFESSIONAL LAND SURVEYOR NO. 2238

STATE OF TEXAS REGISTERED THOMAS FLORES 2238 PROFESSIONAL LAND SURVEYOR

Reference:

VOLUME 3764, PAGE 1260
VOLUME 7853, PAGE 841
VOLUME 9564, PAGE 219
VOLUME 11331, PAGE 2308
VOLUME 11350, PAGE 993
VOLUME 11585, PAGE 2267
VOLUME 11283, PAGE 2405

Job No 762-00.16

SF 11/29/21