

February 04, 2026

G.L. Hunt Foundation Repair
4021 Benbrook Hwy
Fort Worth, TX 76116
Sent via email
Attn: GL Hunt Foundation Repair

Subject: **Foundation Repairs Final
3747 Columbia Dr,
Schertz, TX 78108**

At the request of your foundation repair company, Entek Engineering performed an assessment of the foundation repairs at 3747 Columbia Dr, Schertz, TX 78108. All foundation work and material meet or exceeds with 2021 IRC Code specification for foundation work on residential foundations.

The final confirmation was completed on February 04, 2026. The work has been satisfactorily performed. Refer to attached drawing for final elevations and initial scope of work. Initial scope of work consisted of installing (19) new exterior steel hybrid pressed piers and (14) new exterior/interior steel hybrid "breakout" pressed piers as shown in attached drawing.


I hereby certify and confirm the foundation repair work at 3747 Columbia Dr, Schertz, TX 78108. I further certify that I am a registered Professional Engineer in the State of Texas.

I further certify that the findings and conclusions contained in this report have been, to the best of my knowledge, correctly and completely stated with no bias, and is based upon my observations and experience. No responsibility is assumed for the events that occur after the final inspection and submission of this report and no warranty is either expressed or implied. The limit of liability towards Entek Engineering is the fee paid for this professional opinion

Certified on February 04, 2026.

Respectfully,


Carlos Encarnacion, P.E.
Entek Engineering, LLC



02-04-2026



1



2



3



4

