

Property Disclosure

Case Number: 495-878377
Property Address: 5435 Harefield Dr
San Antonio, TX 78228

Insurability: Uninsurable (UI)
HOA Dues: \$150.00
Period: Quarterly

MPR Property Repairs

Repair all Fire Damages to Property

Repair / Replace HVAC System

Repair / Replace Electrical System

Repair / Replace Plumbing System

Repair / Replace Water Heater

Repair / Replace Roof, Flashing, Gutters and Downspouts

Repair / Replace Exterior Siding, Trim, Soffit and Fascia

Property Disclosures

FIRE DAMAGED PROPERTY - The interior of the property is unsafe to enter. This property is burned, and property is Sold As-Is - Buyer to complete their due diligence and gather all information on this property. Buyer will need to bring property into compliance after closing with County. Any fees will be the responsibility of the Buyer.

Possible Structural issues have been reported, a Structural inspection recommended to determine the extent, as well as the cost of needed repairs. Repairs to be addressed by the purchaser after closing at the purchaser's expense - Buyer to complete their due diligence and gather all pertinent information regarding the property that may impact their purchase decision

Property is NOT located in a FEMA Special Flood Hazard Area. It is the buyers responsibility to verify additional information regarding flood zones and insurance.

Property has an Homeowners Association (HOA). CANTERBURY FARMS HOMEOWNERS ASSOCIATION, INC; FirstService Residential, 210-829-7202

Property is listed as Uninsurable: Estimated MPR Repairs Exceed \$10,000

General Disclosures

All HUD Homes are sold in their AS-IS condition: HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION**

Permission to activate utilities for purposes of the home inspection may be requested from the HUD Field Service Manager after the HUD-9548 sales contract is executed by the seller. Fees for activation may apply.

Properties being purchased with FHA insured financing will require a termite inspection and possible treatment. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or treatment has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection and treatment prior to closing.

Properties built prior to 1978 and being purchased with FHA insured financing will require a lead-based paint inspection and possible stabilization. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or stabilization has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection ,stabilization and clearance letter prior to closing.

This information is accurate based on the data available at the time of listing, and is deemed reliable but not guaranteed. All information should be independently verified.