


HAMILTON POOL

(50' R.O.W.)

(VOL. 9570 PG. 141)

Survey Received and Accepted

By:

By:

RESTRICTIONS:

VOL. 9570 PG. 141–144, D.P.R.
VOL. 11128 PG. 1371, R.P.R.
VOL. 11327 PG. 1047, R.P.R.
VOL. 11327 PG. 1323, R.P.R.
VOL. 11415 PG. 2291, R.P.R.
VOL. 11875 PG. 1481, R.P.R.
VOL. 12254 PG. 1100, R.P.R.

ADDRESS:

1838 HAMILTON POOL

LOT AREA = 5,280 sq.ft.

NOTES:
1. DIRECTIONAL CONTROL LINE = STREET ℄ CONTROL.
2. ═══ = DENOTES CONCRETE CURB.
3. BEARING BASIS = PLAT AS REFERENCED BELOW
4. INSET OR OUTSET DIMENSIONS FOR FENCES, IF ANY, ARE TO CLOSEST EDGE OF POST.
5. THE FOREGOING PROPERTY IS LOCATED WITHIN THE LIMITS OF ZONE X ACCORDING TO THE APPLICABLE FEMA FLOOD INSURANCE RATE MAP #48029C0365 F, DATED SEPTEMBER 29, 2010. ZONE X IS NOT WITHIN A 100 YEAR FLOOD HAZARD ZONE. SCALE: 1"=20'

LAND TITLE SURVEY OF

LOT 9
BLOCK 21
SEALE SUBDIVISION
UNIT–6

BEXAR COUNTY, TEXAS

PLAT REFERENCE: DEED & PLAT RECORDS

VOL. 9570 PAGE 141–144 DATE JUNE 9, 2006

WE, MAVERICK LAND SURVEYING COMPANY, HAVE MADE A SURVEY ON THE GROUND OF THE FOREGOING PROPERTY, AND WE CERTIFY THAT, EXCEPT AS SHOWN, THERE ARE NO VISIBLE ENCROACHMENTS.

BY: _____

Maverick Land Surveying Co.

1856 Lockhill Selma, Suite 105, San Antonio, Texas 78213

(210) 342-9455, Fax 342-9524

©1990-20121, Maverick Land Surveying Co.

F.W. BY: J.G., Jr.

DATE 3-21-12

JOB NO. 45873-02

DRN.: R.S. CKD.: D.S.