



Customer Name: Anita Baldwin

Address: 6943 Washita Way San Antonio, TX 78256

Phone #: 210-748-4189

E-mail: anita.baldwin@yahoo.com

Date: 08/03/2026

To Whom It May Concern,

After our inspector, Allen Alexander, evaluated the property there were no m
relation to the structural foundation. A thorough visual inspection of the exter
the property was conducted it was concluded and there are no suggestions f
or adjustments needed at this time. If you have any questions or concerns al
free to reach out to the inspector, Allen, @ 210-336-3947.

Hercules Foundation Repair, LLC.

Office #: 210-556-6767

E-mail: herculesfoundationtx@gmail.com